

## Characterization of Freeze-Thaw Damage in Concrete Using Contactless Ultrasonic Measurements

\*Homin Song<sup>1)</sup>, Sangmin Lee<sup>2)</sup>, Yu Song<sup>3)</sup>, and John S. Popovics<sup>4)</sup>

<sup>1)</sup> Department of Civil and Environmental Engineering, Gachon University,  
Seongnam-si, Gyeonggi-do 13120, Korea

<sup>2), 4)</sup> Department of Civil and Environmental Engineering, University of Illinois Urbana-Champaign, Urbana, IL 61801, USA

<sup>3)</sup> Department of Civil and Environmental Engineering, University of California Los Angeles, Los Angeles, CA 90095, USA

<sup>1)</sup> [hominson@gachon.ac.kr](mailto:hominson@gachon.ac.kr)

### ABSTRACT

We present work to characterize distributed cracking damage in concrete caused by freeze-thaw (F-T) cycles. Rayleigh wave scattering behaviors are investigated using numerical simulations to understand the interaction between incident ultrasonic Rayleigh waves and F-T damage. A contactless ultrasonic scanning measurement system that utilizes a multi-channel MEMS microphone array is used to collect ultrasonic scanning data from concrete specimens subjected to F-T cycles. Then, a data processing approach that extracts damage-sensitive scattering components from the collected ultrasonic scanning data is employed to characterize the extent of F-T damage in the tested concrete samples. The proposed approach is evaluated using other nondestructive and destructive test methods including ultrasonic pulse velocity (UPV) measurements, dynamic modulus testing, and petrographic analysis. The results confirm the effectiveness of the approach to characterize F-T damage in concrete. The fully contactless ultrasonic scanning measurement system can potentially characterize F-T damage within concrete structures *in situ* without preparing separate samples.

### REFERENCES

Song, H., Park, J. and Popovics, J.S. (2020), "Development of a MEMS ultrasonic microphone array system and its application to compressed wavefield imaging of concrete", *Smart Mater. Struct.*, **29**, 105011.

---

<sup>1)</sup> Assistant Professor

<sup>2)</sup> Graduate Student

<sup>3)</sup> Postdoctoral Researcher

<sup>4)</sup> Professor

Li, S., Chen, G., Ji, G. and Lu, Y. (2014), "Quantitative damage evaluation of concrete suffered freezing-thawing by DIP technique", *Const. Build. Mat.*, **69**, 177-185.